

Service History



Vehicle data

VIN	TMBNM65J3B5013233
Delivery date:	2011-03-10
Next General Inspection	2026-11
Next Emissions Test	2026-11
Model	5J71F4

History

Show 100 entries

▼

ALL

MAINTENANCE

DIGITAL MAINTENANCE SCHEDULE

CONCERNS

PDF

Digital Maintenance Schedule ▼

Repair order date:
2024-11-18

Mileage:
23287

Repair order no.:
2024019555

Service record:
Inventory
Inspection

Additional work

#	Line item	Description
1	85185580	Dust and pollen filter
2	01400050	Brake fluid service
3	28705588	Spark plug
4	85185580	Dust and pollen filter
5	24245550	Air cleaner element



Invoice

Repair order date:
2024-09-30

Mileage:
23287

Repair order no.:
2401955501

Invoice no.:
5567228218

Comment
Maintenance

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	01050000	Inventory Inspection .	X	0000		0
2	85185580	STAUB-U.POLLENFILTER ERSETZEN	-	0000		0
3	01400050	Brake fluid service .	X	0000		0
4	24245550	Air cleaner element replaced	-	0000		0
5	28705588	4 ZÜNDKERZE ERSETZEN	-	0000		0

Parts Item

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	03C115561H	Oil filter	1.00	C	OWN	01		0
2	OEL003	OW30 OEL	3.60	F	OWN	Q1		0
3	6Q0819653B	Dust filt.	1.00	C	OWN	01		0
4	B 000DS	Bremsflüssigkeit	1.15	C	OWN	02		0
5	6R0129620A	Airfilter	1.00	C	OWN	01		0
6	03F905600A	Spark plug	4.00	C	OWN	02		0
7	ZUB100	SCHEIBKLAR	1.00	F	OWN	02		0



Invoice ▼

Repair order date:
2023-01-18

Mileage:
23157

Repair order no.:
2300107401

Invoice no.:
5567173663

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	27060100	Battery checked	-	0000		0
2	27061900	Battery removed+reinstalled	-	0000		0
3	27065550	Battery replaced	-	0000		0

Parts Item

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	000915105DB	Battery	1.00	C	OWN	03		0

Concern ▼

Repair order date:
2022-10-12

Mileage:
23108

Repair order no.:
2022020550

Concern ID:
154145540

Customer concern	Gangschaltung 1 Gang und Rückwertsgang Probleme beim schalten
Customer code	
Workshop diagnosis	
Workshop code	
Replacement part for repair	



Invoice

Repair order
date:
2022-10-12

Mileage:
23115

Repair order
no.:
2202055001

Invoice no.:
5567168111

Comment
Maintenance

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	01050000	Inventory Inspection .	X	0000		0
2	85185580	Staub-u.Pollenfilter ersetzen	-	0000		0
3	01400050	Brake fluid service .	X	0000		0
4	01000399	Abgasuntersuchung (Verbundprüfung)	-	0000		0

Parts Item

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	03C115561H	Oil filter	1.00	C	OWN	01		0
2	N 90813202	Screw	1.00	C	OWN	01		0
3	OEL003	OW30 OEL	3.60	F	6	Q1		0
4	ZUB100	SCHEIBKLAR	1.00	F	6	02		0
5	3T0050200 F5A	AEROSOL-SPRA	2.00	C	OWN	19		0
6	6Q0819653B	Dust filt.	1.00	C	OWN	01		0
7	B 000DS	Bremsflüssigkeit	1.15	C	OWN	02		0



Invoice ▼

Repair order
date:
2022-04-19

Mileage:
30000

Repair order
no.:
2200775601

Invoice no.:
5567155552

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	06000499	Saisonaler Fahrzeug-Check	-	0000		0

Invoice ▼

Repair order
date:
2020-10-27

Mileage:
22483

Repair order
no.:
2000708701

Invoice no.:
5587054677

Comment
Maintenance

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	01220000	DIALOGANNAHME DURCHGEFÜHRT	-	0000		0
2	01050000	Inventory Inspection .	X	0000		0
3	99001099	FUSSRAUM AUSGESAUGT OHNE BERECHNUNG	-	0000		0
4	99001199	AUSSENWÄSCHE OHNE BERECHNUNG	-	0000		0

Parts Item

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	OEL003	Liter Öl 0W-30	3.60	V	OWN	60		0
2	03C115561H	Oil filter	1.00	C	6	01		0
3	N 90813202	Screw	1.00	C	6	01		0



Invoice

Repair order
date:
2020-02-07

Mileage:
21996

Repair order
no.:
2O00106001

Invoice no.:
5587048431

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	01220000	DIALOGANNAHME DURCHGEFÜHRT	-	0000		0
2	01000699	AU - Aktion DEKRA	-	0000		0



Invoice

Repair order
date:
2019-09-27

Mileage:
21554

Repair order
no.:
1900733901

Invoice no.:
5587044719

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	01220000	DIALOGANNAHME DURCHGEFÜHRT	-	0000		0
2	06003199	WINTER-CHECK	-	0000		0
3	44000499	4 RÄDER AUS- UND EINGEBAUT AKTIONSP	-	0000		0
4	LADUNG	LADUNG	-	0000		0
5	44002199	1 REIFENMONTAGE AUF FELGE INCL. WUC	-	0000		0
6	92000299	2 WISCHERBLÄTTER AUS - U. EINGEBAUT	-	0000		0

Parts Item

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	ZTW195555HFW30	REIFEN FIR	1.00	V	OWN	43		0
2	839601361	Rubber val	1.00	C	6	03		0
3	5J1998001	Wip. blade	1.00	C	6	13		0



Invoice

Repair order
date:
2019-09-16

Mileage:
21404

Repair order
no.:
1900697701

Invoice no.:
5587043811

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	01220000	DIALOGANNAHME DURCHGEFÜHRT	-	0000		0
2	44000199	1 RAD AUS- UND EINGEBAUT	-	0000		0



Invoice ▼

Repair order
date:
2019-04-16

Mileage:
20872

Repair order
no.:
1900316601

Invoice no.:
5587040394

Comment
Maintenance

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	01220000	DIALOGANNAHME DURCHGEFÜHRT	-	0000		0
2	01050000	Inventory Inspection .	X	0000		0
3	28705588	4 Zündkerzen ersetzen	-	0000		0
4	85185580	Staub-u.Pollenfilter ersetzen	-	0000		0
5	24245550	Air cleaner element replaced	-	0000		0
6	01400050	Brake fluid service .	X	0000		0
7	99001199	Aussenwäsche ohne Berechnung	-	0000		0
8	99001099	FUSSRAUM AUSGESAUGT OHNE BERECHNUNG	-	0000		0

Parts Item

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	OEL003	Liter Öl 5W-30	3.60	V	OWN	60		0
2	03C115561H	Oil filter	1.00	C	6	01		0
3	N 90813202	Screw	1.00	C	6	01		0
4	03F905600A	Spark plug	4.00	C	6	02		0
5	6Q0819653B	Dust filt.	1.00	C	6	01		0
6	6R0129620A	Airfilter	1.00	C	6	01		0
7	B 000DS	Liter Bremsflüssigkeit	1.15	C	6	02		0
8	Z 093115	Verbandstasche	1.00	C	6	53		0



Invoice ▼

Repair order
date:
2019-03-14

Mileage:
20680

Repair order
no.:
1900208601

Invoice no.:
5587039592

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	01220000	DIALOGANNAHME DURCHGEFÜHRT	-	0000		0
2	44000499	4 RÄDER AUS- UND EINGEBAUT AKTIONSP	-	0000		0
3	06003299	FRÜHJAHR-S-CHECK	-	0000		0
4	92000299	2 Wischerblätter aus - u. eingebaut	-	0000		0

Parts Item

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	5J1998001	Wip. blade	1.00	C	6	13		0

Invoice ▼

Repair order
date:
2018-10-18

Mileage:
20175

Repair order
no.:
1800819901

Invoice no.:
5587034860

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	06003199	WINTER-CHECK	-	0000		0



Invoice ▼

Repair order
date:
2018-02-12

Mileage:
19381

Repair order
no.:
1800112101

Invoice no.:
5587028457

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	01000599	AU - Aktion TÜV	-	0000		0

Invoice ▼

Repair order
date:
2018-01-22
Parts Item

Mileage:
20100

Repair order
no.:
1800054701

Invoice no.:
5587027452

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	5J7955425	Wiperblade	1.00	C	6	13		0



Invoice ▼

Repair order
date:
2017-11-13

Mileage:
18866

Repair order
no.:
1700922701

Invoice no.:
5587026336

Comment
Maintenance

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	01220000	Dialogannahme durchgeführt .	-	0000		0
2	01050000	Inventory Inspection .	X	0000		0
3	99001199	AUSSENWÄSCHE OHNE BERECHNUNG	-	0000		0
4	99001099	FUSSRAUM AUSGESAUGT OHNE BERECHNUNG	-	0000		0

Parts Item

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	6Q6955435D	Cap	1.00	C	6	03		0
2	5J7955425	Wiperblade	1.00	C	6	13		0
3	6Q6955707C	Wiper arm	1.00	C	6	03		0
4	OEL003	Liter Öl 5W30	3.60	V	OWN	60		0
5	N 90813202	Screw	1.00	C	6	01		0
6	03C115561J	Oil filter	1.00	C	6	01		0



Invoice ▼

Repair order date:
2017-10-19

Mileage:
18800

Repair order no.:
1700844401

Invoice no.:
5587025577

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	44000499	4 RÄDER AUS- UND EINGEBAUT AKTIONSP	-	0000		0

Invoice ▼

Repair order date:
2017-04-24

Mileage:
17727

Repair order no.:
1700309601

Invoice no.:
5587020771

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	55550000	Club 5 Mitglied	-	0000		0
2	55557799	Skoda Sicherheits-Check Club 5	-	0000		0
3	44449904	4 RÄDER AUS- UND EINGEBAUT AKTIONSP	-	0000		0



Invoice ▼

Repair order date:
2016-11-02

Mileage:
16875

Repair order no.:
1600725601

Invoice no.:
5587015981

Comment
Maintenance

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	44449904	4 RÄDER AUS- UND EINGEBAUT AKTIONSP	-	0000		0
2	06003199	WINTER-CHECK	-	0000		0
3	01400000	Brake fluid service .	X	0000		0

Parts Item

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	B01	Liter Bremsflüssigkeit	1.15	C	6	02		0



Invoice ▼

Repair order
date:
2016-05-19

Mileage:
16010

Repair order
no.:
1600593801

Invoice no.:
5557019822

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	63691900	Rear bumper cover removed+reinstall	-	0000		0
2	63501950	Rear bumper removed+reinstalled	-	0000		0
3	63731950	Rear carrier removed+reinstalled	-	0000		0
4	63731950	Rear carrier removed+reinstalled	-	0000		0
5	94311900	Taillight removed+reinstalled	-	0000		0
6	66761950	Rear wheel housing liner rem+reins	-	0000		0
7	44051900	Wheel removed+reinstalled	-	0000		0
8	70301900	Luggage compartment cover rem+reins	-	0000		0
9	70061900	Luggage compartment rear trim rem+r	-	0000		0
10	70391900	Lock carrier cover removed+reinstal	-	0000		0
11	70681900	C-pillar trim removed+reinstalled	-	0000		0
12	70691950	D-pillar trim removed+reinstalled	-	0000		0
13	70751900	Rear side trim removed+reinstalled	-	0000		0
14	99999998	SEITENWAND LINKS HINTEN INSTANDSETZ	-	0000		0
15	51017501	Body cavity sealcoated	-	0000		0



#	Line item	Description	Maintenance	Paint	Sales code	Package
16	64757750	Side window covered	-	0000		0
17	51017133	Body painting prepared	-	0000		0
18	51017193	Body painting prepared	-	0000		0
19	63696151	Rear bumper cover new part painted	-	0000		0
20	53557903	Rear side panel painted	-	0000		0
21	66775500	STEINSCHLAGECKE LINKS HINTEN ERSETZ	-	0000		0
22	99999998	REPARATUR GEM HERSTELLERVORGABE	-	0000		0
23	99999997	LACKIERUNG MIT ORIGINAL LACKPRODUKT	-	0000		0

Parts Item

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	D 330KD2A1	Preserv.	1.00	V	OWN	02		0



Invoice

Repair order
date:
2016-05-11

Mileage:
16010

Repair order
no.:
1600286801

Invoice no.:
5587012495

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	99999999	FAHRZEUGVERBRINGUNG	-	0000		0

Parts Item

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	6N0809966A	Nut	13.00	C	6	01		0
2	5J7807394	Piece	1.00	C	6	14		0
3	5J7807393	Piece	1.00	C	6	14		0
4	5J7807905A	Foil	1.00	C	6	14		0
5	5J7807906A	Foil	1.00	C	6	14		0
6	5J7853336	Foil	1.00	C	6	18		0
7	5J7807179	Trim	1.00	C	6	13		0
8	5J7807864	Ret strip	1.00	C	6	14		0
9	5J7807863	Ret strip	1.00	C	6	14		0
10	5J7807421D	Cover	1.00	C	6	14		0
11	5J7853335	Foil	1.00	C	6	18		0
12	1Z0860091J	Nut	6.00	C	6	11		0
13	1Z0860505D	Bolt	10.00	C	6	11		0
14	N 90648704	Bolt	10.00	C	6	01		0
15	N 90094201	Speed nut	2.00	C	6	01		0
16	N 90780904	Bolt	10.00	C	6	01		0
17	N 10700901	Rivet	10.00	C	6	01		0



#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
18	N 10318001	Nut	1.00	C	6	01		0
19	N 90536901	Rivet	8.00	C	6	01		0

Invoice

Repair order date:
2016-04-14

Mileage:
15806

Repair order no.:
1600224401

Invoice no.:
5587011556

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	44000499	4 RÄDER AUS- UND EINGEBAUT AKTIONSP	-	0000		0
2	57082500	Key programmed	-	0000		0



Invoice

Repair order
date:
2016-03-01

Mileage:
15444

Repair order
no.:
1600127301

Invoice no.:
5587010748

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	01220000	DIALOGANNAHME DURCHGEFÜHRT	-	0000		0
2	01000199	AU - Aktion DEKRA	-	0000		0

Parts Item

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	5J0837219 INB	Key	1.00	C	6	18		0



Invoice ▼

Repair order
date:
2015-11-02

Mileage:
14622

Repair order
no.:
1500656901

Invoice no.:
5587008226

Comment
Maintenance

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	01220000	Dialogannahme durchgeführt	-	0000		0
2	01050000	Inventory Inspection .	X	0000		0
3	85185580	Staub-u.Pollenfilter ersetzt.	-	0000		0
4	44000499	4 RÄDER AUS- UND EINGEBAUT AKTIONSP	-	0000		0
5	99001199	AUSSENWÄSCHE OHNE BERECHNUNG	-	0000		0
6	99001099	FUSSRAUM AUSGESAUGT OHNE BERECHNUNG	-	0000		0

Parts Item

#	Line item	Description	Quantity	Production code	Factory Order	Parts Group	Sales code	Package
1	OEL003	Liter Öl LL3 5W30	3.60	F	6	00		0
2	N 90813202	Screw	1.00	C	6	01		0
3	03C115561J	Oil filter	1.00	C	6	01		0
4	6Q0819653B	Dust filt.	1.00	C	6	01		0



Invoice ▼

Repair order date:
2015-04-17

Mileage:
11822

Repair order no.:
1500219601

Invoice no.:
5587004252

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	44000499	4 RÄDER AUS- UND EINGEBAUT AKTIONSP	-	0000		0

Invoice ▼

Repair order date:
2014-11-11

Mileage:
11189

Repair order no.:
1400181801

Invoice no.:
5587001308

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	44000499	4 RÄDER AUS- UND EINGEBAUT AKTIONSP	-	0000		0

Invoice ▼

Repair order date:
2010-09-03

Mileage:
0

Repair order no.:
6185

Invoice no.:
754

Labor Operation

#	Line item	Description	Maintenance	Paint	Sales code	Package
1	01010099	ÜBERGABE INSPEKTION	-	0000		0